PRINTED: 10/27/2009 FORM APPROVED

Bureau of Health Care Quality & Compliance

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIE IDENTIFICATION NUI			(X2) MULTIPLE CONSTRUCTION A. BUILDING		(X3) DATE SURVEY COMPLETED		
NVN642HOS		NVN642HOS		B. WING		10/08/2009	
NORTHEASTERN NV REGIONAL HOSPITAL				DDRESS, CITY, STATE, ZIP CODE RECART BLVD V 89801			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FUL REGULATORY OR LSC IDENTIFYING INFORMATIO			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (X5) COMPLETE DATE		COMPLETE
S 000	Initial Comments		S 000				
	Surveyor: 13812 This Statement of Deficiencies was generated as a result of a State licensure focus survey conducted in your facility on 10/5/09 and finalized on 10/8/09, in accordance with Nevada Administrative Code, Chapter 449, Hospitals. A Plan of Correction (POC) must be submitted. The POC must relate to the care of all patients and prevent such occurrences in the future. The intended completion dates and the mechanism(s) established to assure ongoing compliance must be included. Monitoring visits may be imposed to ensure on-going compliance with regulatory requirements.						
	The findings and conclusions of any investigation by the Health Division shall not be construed as prohibiting any criminal or civil investigations, actions or other claims for relief that may be available to any party under applicable federal, state or local laws.						
S 128 SS=E	NAC 449.327 Sterile Supplies and Medical Equipment		S 128				
	stores its supplies and develop systems and consistent with: (c) When applicable, guidelines for the use equipment. This Regulation is not Surveyor: 22046 Based on review of the		nall he r: rating				

If deficiencies are cited, an approved plan of correction must be returned within 10 days after receipt of this statement of deficiencies.

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

PRINTED: 10/27/2009

FORM APPROVED Bureau of Health Care Quality & Compliance STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING B. WING NVN642HOS 10/08/2009 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2001 ERRECART BLVD NORTHEASTERN NV REGIONAL HOSPITAL **ELKO, NV 89801** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) (X4) ID ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) S 128 Continued From page 1 S 128 the manufacturer's representative, the facility failed to conduct periodic maintenance of the steam autoclaves in accordance with the manufacturer's recommendations: 1. The inside of the chamber was not washed with a mild detergent solution on a regular basis. 2. The chamber drain strainer was removed to clean out lint and sediment on a daily basis. Severity 2 Scope 2